

Inspection Photos
Location Name: Great Western Pad 4
Location ID: 333028



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Great Western Pad 4
Location ID: 333028



Photo 3: Tank Battery Sign



Photo 4: Tank Battery/inadequate berms

Inspection Photos
Location Name: Great Western Pad 4
Location ID: 333028



Photo 5: No NFPA placard/tank NOT anchored



Photo 6: Tank NOT anchored

Inspection Photos
Location Name: Great Western Pad 4
Location ID: 333028



Photo 7: Tanks NOT anchored



Photo 8: Separator NOT anchored