

MARALEX RESOURCES, INC.– 53255
API# 05-077-08215 LIPAN WASH UNIT #1-14-2-2
Inspection Date : 11/4/2019



Overview of location looking NE.



Wellhead with Pump jack.

MARALEX RESOURCES, INC.– 53255
API# 05-077-08215 LIPAN WASH UNIT #1-14-2-2
Inspection Date : 11/4/2019



Blowdown pit with fence and netting.



Separator and Meter housing with sign looking W

MARALEX RESOURCES, INC.– 53255
API# 05-077-08215 LIPAN WASH UNIT #1-14-2-2
Inspection Date : 11/4/2019



SW anchor and Meter housing with sales line riser. Looking N.



Trash and gravel dumped off NW corner of location.