

MARALEX RESOURCES, INC.– 53255
API# 05-077-08501 LIPAN WASH UNIT #10-16-2-2
Inspection Date : 11/4/2019



Overview of location. NE anchor looking looking SW.



Wellhead with fencing and sign

MARALEX RESOURCES, INC.– 53255
API# 05-077-08501 LIPAN WASH UNIT #1-16-2-2
Inspection Date : 11/4/2019



Blowdown pit with fence and netting.



Produced water tank

MARALEX RESOURCES, INC.– 53255
API# 05-077-08501 LIPAN WASH UNIT #1-16-2-2
Inspection Date : 11/4/2019



Meter housing and Separator



Trash and Meter housing panels/doors blown off.