

Inspection Photos
Location Name: State 41-14-1
Location ID: 424085



Photo 1. Overview of location taken facing southeast. Site degradation apparent.



Photo 2. Tubing stored at wellhead.

