

Inspection Photos
Location Name: Greasewood 08-18H
Location ID: 423895



Photo 1 – Pumping Unit



Photo 2 – Tank Battery

Inspection Photos
Location Name: Greasewood 08-18H
Location ID: 423895



Photo 3 – Unmarked 2" Risers



Photo 4 –Unmarked 2" Risers



Inspection Photos
Location Name: Greasewood 08-18H
Location ID: 423895



Photo 5 – Unmarked 3" Risers



Photo 6 – Unmarked 2" Risers



Inspection Photos
Location Name: Greasewood 08-18H
Location ID: 423895



Photo 7 – Unmarked 1" and 2" Risers



Photo 8 – Containment is vulnerable to wildlife intrusion.

