

Inspection Photos
Location Name: Frank Trust 11-11H
Location ID: 420027



Photo 1 – Pumping Unit



Photo 2 – Tank Battery



Inspection Photos
Location Name: Frank Trust 11-11H
Location ID: 420027



Photo 3 – Sign does not reflect current Operator




Photo 4 – Tank Content and Capacity label is faded no longer legible. NFPA Label also needs replaced.

Inspection Photos
Location Name: Frank Trust 11-11H
Location ID: 420027



Photo 5 – Tank Content and Capacity label is faded no longer legible. NFPA Label also needs replaced.



Photo 6– Tubing String on the North West of the Tank Battery Berm.

Inspection Photos
Location Name: Frank Trust 11-11H
Location ID: 420027



Photo 7 – Rods at wellhead