

Inspection Photos
Location Name: Payne C #1A
API: 05-067-09332



Dismantled pump jack at the Payne C #1A. Plunger lift in use on well.



Stained soil at base of secondary containment for lube oil container.

Inspection Photos
Location Name: Payne C #1A
API: 05-067-09332



Free standing sign near open topped below grade tank in NE corner of location.

Free standing sign near open topped below grade tank in NW corner of location.