

Inspection Photos
Location Name: Hiawatha Middle Oil 13 F Wilson
Location ID: 312834



Photo 1. Overview of location taken facing west. Heated separator approximately 15 feet from wellhead.

