

**Inspection Photos**  
**Location Name: Ruby #2**  
**Location ID: 320521**



**Photo 1 WH. All production equipment and flow lines have been removed from well head. Unused equipment: well head parts and tubing on location.**



**Photo 2 TNK BTRY**

**Inspection Photos**  
**Location Name: Ruby #2**  
**Location ID: 320521**



**Photo 3 it appears bird netting has been repaired on produced water tank**



**Photo 4 Sep/ meter runs and ECD**