

Inspection Photos
Location Name: Sledge C 9-29
Location ID: 309877



Colorado Oil and Gas Conservation Commission
40.3339, -104.56053, 4694.7ft, 276°
09/10/2019 08:42:00 AM



Colorado Oil and Gas Conservation Commission
40.3339, -104.56052, 4678.8ft, 356°
11/06/2019 09:28:14 AM

Photo #1 East Pit sign with no Capacity. On 9/10/19

Photo #2 East Pit sign with Capacity. On 11/6/19