

**Inspection Photos**  
**Location Name: State 11**  
**Location ID: 336425**



**Photo #1 WH sign**



**Photo #2 PU broken belts removed**



**Inspection Photos**  
**Location Name: State 11**  
**Location ID: 336425**



**Photo #3 Stained soil at WH appears to have been removed**