

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2019

Submitted Date:

10/31/2019

Document Number:

696101492

FIELD INSPECTION FORMLoc ID 413457 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412513	WELL	SI	04/01/2019	OW	123-30597	NORTH PLATTE 31-34	SI
423532	WELL	SI	04/01/2019	GW	123-33613	North Platte 32-34	SI

General Comment:

This is a WELL & BATTERY inspection.

Well(s): 2 ; Shut-In | SI.

Battery: Shut-down | Inactive

Centralized Battery serves 2 Location IDs (413457, 413974).

(Well(s): 4 ; 2: Shut-In | SI ; 2: Temporarily Abandoned | TA).

(1: Other well associated w/ Location ID #413974 is connected to another Battery/Facility.)

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign with company & well name NOT posted at North Platte 31-34 wellsite. Refer to Rule 210.b. (60 Days). * Post sign with company & well name at North Platte 31-34 wellsite. Comply w/ Rule 210.b. Corrective Action date: 12/30/2019. See photo #1.			
Corrective Action:	* Post sign with company & well name at North Platte 31-34 wellsite. Comply w/ Rule 210.b. See photo #1.		Date:	12/30/2019
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:			Date:	
Type	BATTERY			
Comment:				
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	<input style="width: 100%;" type="text"/>			
Corrective Action:	<input style="width: 100%;" type="text"/>			Date: <input style="width: 100%;" type="text"/>
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No <input type="checkbox"/>				
Comment:	<input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	2 - Wellsites: Iron panel			
Corrective Action:			Date:	
Type	SEPARATOR			
Comment:	Surroinded by earth berms.			
Corrective Action:			Date:	
Equipment:				
Type: Gas Meter Run	# 1		corrective date	
Comment:	<input style="width: 100%;" type="text"/>			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 4		
Comment:	Controls crude oil tank VOCs. Pilots: OFF Shut-down		
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	2 - Wellsites		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	2 - Wellsites: Appears plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	ECD scrubber		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 2 Location IDs (413457, 413974).				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:			Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:			Date:		

Paint

Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: [Shares berms w/ crude oil tanks.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.363892,-104.413841

Comment: [Equalizer lines connect crude oil tanks.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: [Shares berms w/ produced H2O vault.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected FacilitiesFacility ID: 412513 Type: WELL API Number: 123-30597 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Shut-In | SI. Observed production valves closed.
COGCC records indicate last production: 03/2019.Corrective Action: Date: Facility ID: 423532 Type: WELL API Number: 123-33613 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Shut-In | SI. Observed production valves closed.
COGCC records indicate last production: 03/2019.Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 10/30/2019 at approximately 16:32 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte /32-34 Location ID: 413457 Well Names: North Platte 31-34, North Platte 32-34 API: 05-123-30597, 05-123-33613 Location County: Weld County, Colorado Weather: Clear w/ prior snow cover</p> <p>While there, I observed: Well(s): 2 ; Shut-In SI. Battery: Shut-down Inactive</p> <p>Centralized Battery serves 2 Location IDs (413457, 413974). (Well(s): 4 ; 2: Shut-In SI ; 2: Temporarily Abandoned TA). (1: Other well associated w/ Location ID #413974 is connected to another Battery/Facility.)</p> <p>During this inspection, the following possible compliance issues were observed: 1.) Sign with company & well name NOT posted at North Platte 31-34 wellsite. Refer to Rule 210.b. (60 Days). * Post sign with company & well name at North Platte 31-34 wellsite. Comply w/ Rule 210.b. Corrective Action date: 12/30/2019. See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/31/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402227996	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977876
402229215	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978714

402229240	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978726
402229271	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978756
402229282	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978775
696101493	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977875