

Inspection Photos
Location Name: Federal 8-27
Location ID: 324683



Photo 1. Overview of location taken facing northeast.



Photo 2. Stained soil at wellhead.

