

Inspection Photos
Location Name: LDS 20-8
API ID: 123-21605



Photo #1 Wellhead , Sign, & Weeds. On 9/23/19

Photo #2 Wellhead , Sign, & Weeds. On 11/7/19

Inspection Photos
Location Name: LDS 20-8
API ID: 123-21605



Colorado Oil and Gas Conservation Commission
40.23617, -104.57014, 4680.5ft, 314°
11/07/2019 08:11:40 AM

Photo #3 Red PTA tag & Yellow Decommission Facility tag