

Inspection Photos

API: 05-071-07543

05-071-07716

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/5/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-07543 | Date: 11/5/2019

Inspection Photos



Photo 1. Facing north at the beginning of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07543 | Date: 11/5/2019

Inspection Photos



Photo 2. There is an area of erosion along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07543 | Date: 11/5/2019

Inspection Photos



Photo 3. There is a second property gate along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07543 | Date: 11/5/2019

Inspection Photos



Photo 4. Facing east down the success road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07543 | Date: 11/5/2019

Inspection Photos



Photo 5. There is a culvert filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07543 | Date: 11/5/2019

Inspection Photos



Photo 6. Facing southeast toward the location. There is a diversion ditch along the top of the cut slope with rock rip/rap installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07543 | Date: 11/5/2019

Inspection Photos



Photo 7. Facing south toward the cut slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07543 | Date: 11/5/2019

Inspection Photos



Photo 8. Facing north at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07543 | Date: 11/5/2019

Inspection Photos



Photo 9. Facing south along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07543 | Date: 11/5/2019

Inspection Photos



Photo 10. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07543 | Date: 11/5/2019