

Interim Reclamation and Stormwater Inspection

November 4, 2019

Operator: LONGS PEAK RESOURCES LLC- #10611

Location ID: 440192

Inspection Document #: 697500784

Weld County, CO

NWNE Section 35 T12N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Pismo East
/35-26-23-2-1CH
Location ID: 440192



Photo 1. Photo taken from the eastern interim area, facing North. Photo illustrates Operator has performed interim reclamation to reduce areas only needed for production operations per Rule 1003. Note: Appears straw mulch was crimped as an erosion control but has already blown off location which will not ensure the seeded soil is stabilized. COGCC staff would recommend re-installing erosion controls and using long-fiber weed-free mulch.



Photo 2. Photo taken from the eastern interim area, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Pismo East
/35-26-23-2-1CH
Location ID: 440192



Photo 3. Photo taken from the western well pad, facing South. Photo illustrates that portions of the western and southwestern well pad can be further reduced in size to comply with Rule 1003. Currently, the Operator is storing gravel along a portion of this area where interim reclamation shall be performed.

Inspection Photos
Location Name: Pismo East
/35-26-23-2-1CH
Location ID: 440192



Photo 4. Photo taken from the southwestern well pad, facing South. Operator shall remove this gravel pile from the interim area.