

Inspection Photos
Location Name: Lind 20-24
Location ID: 302373



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos
Location Name: Lind 20-24
Location ID: 302373



Photo 3: Labeling visible on crude oil tank



Photo 4: Labeling visible on crude oil tank



Inspection Photos
Location Name: Lind 20-24
Location ID: 302373



Photo 5: Labeling visible on tanks.



Photo 6: Weeds cut. Debris left from dead weeds

Inspection Photos
Location Name: Lind 20-24
Location ID: 302373



Photo 7: Weeds cut. Debris from dead weeds.



Photo 8: Stained soil in separator house.



Inspection Photos
Location Name: Lind 20-24
Location ID: 302373



Photo 9: Stained soil/bucket removed (middle separator)




Photo 10: Stained soil in east separator

Inspection Photos
Location Name: Lind 20-24
Location ID: 302373



Photo 11: Stained soil removed



Photo 12: Wellhead Sign



Inspection Photos
Location Name: Lind 20-24
Location ID: 302373



Photo 13: Wellhead




Photo 14: Stained soil