

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/06/2019

Submitted Date:

11/07/2019

Document Number:

679705972

**FIELD INSPECTION FORM**

Loc ID 335883	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: 100264 Name of Operator: XTO ENERGY INC Address: 110 W 7TH STREET City: FORTH WORTH State: TX Zip: 76102				<b>Findings:</b> 15 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Reid, Van		van_reid@xtoenergy.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287332	WELL	DG	05/14/2013	GW	103-10928	FREEDOM UNIT 197-31A1	TA
287333	WELL	DG	01/01/2012	GW	103-10927	FREEDOM UNIT 197-31A2	TA
287334	WELL	TA	02/01/2017	GW	103-10926	FREEDOM UNIT 197-31A4	TA
287335	WELL	DG	01/01/2012	GW	103-10925	FREEDOM UNIT 197-31A5	TA
287336	WELL	DG	05/14/2013	GW	103-10924	FREEDOM UNIT 197-31A6	TA
287337	WELL	DG	10/01/2012	GW	103-10923	FREEDOM UNIT 197-31A7	TA
287338	WELL	DG	05/14/2013	GW	103-10922	FREEDOM UNIT 197-31A9	TA
287339	WELL	DG	01/01/2012	GW	103-10921	FREEDOM UNIT 197-31A3	TA
287340	WELL	DG	09/26/2014	GW	103-10920	FREEDOM UNIT 197-31A8	TA
287341	WELL	DG	12/11/2012	GW	103-10919	FREEDOM UNIT 197-31A10	TA

**General Comment:**

COGCC Inspection Report Summary.

On 11-6-2019 at approximately 13:20, inspector Rick Moran, conducted a routine inspection at XTO wells pad Freedom Unit 197-31A in Rio Blanco county.

The following compliance issues were observed:

1) "911" missing on location sign. Photo 3. Complete by 12-7-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705972.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Missing "911" on location sign.

Corrective Action: Install sign to comply with Rule 210.b.

Date: 12/07/2019

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 6		
Comment:	Three undeployed 400 bbl tanks and 3 flowline spools.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Inspected Facilities**

Facility ID: 287332 Type: WELL API Number: 103-10928 Status: DG Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Casing capped. No flowline.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287333 Type: WELL API Number: 103-10927 Status: DG Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Casing capped. No flowline.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287334 Type: WELL API Number: 103-10926 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Braden head on well.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287335 Type: WELL API Number: 103-10925 Status: DG Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Casing capped. No flowline.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287336 Type: WELL API Number: 103-10924 Status: DG Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Casing capped. No flowline.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287337 Type: WELL API Number: 103-10923 Status: DG Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Casing capped. No flowline.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287338 Type: WELL API Number: 103-10922 Status: DG Insp. Status: TA

**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Corrective Action: 

Date: \_\_\_\_\_

Facility ID: 287339 Type: WELL API Number: 103-10921 Status: DG Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Corrective Action: 

Date: \_\_\_\_\_

Facility ID: 287340 Type: WELL API Number: 103-10920 Status: DG Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Corrective Action: 

Date: \_\_\_\_\_

Facility ID: 287341 Type: WELL API Number: 103-10919 Status: DG Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Corrective Action: 

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	287448	1433528	
	287448	1433528	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705973	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983559">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983559</a>