

Inspection Photos Location #335542



location



location



Inspection Photos Location #335542




Holes in liner



Holes in liner



Inspection Photos Location #335542



Holes in liner



Condensate in drip pan next to tank burner that is running



Inspection Photos Location #335542



Condensate in drip pan next to tank burner that is running



Needs slope stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos Location #335542



Open hole for wildlife to enter

