

Inspection Photos
Location Name: Hingley #1
Location ID: 333213



Photo 1 WH & sign weeds have been cut



Photo 2 ECD weeds have been cut



Inspection Photos
Location Name: Hingley #1
Location ID: 333213



Photo 3 TB weeds have been cut



Photo 4 TB signs



Inspection Photos
Location Name: Hingley #1
Location ID: 333213



Photo 5 Heated Horz. Sep. weeds have been cut



Photo 6 Sep. house stained soil removed/ plumbing has been tightened

Inspection Photos
Location Name: Hingley #1
Location ID: 333213



Photo 7 Gas meter run weeds have been cut/pellet removed



Photo 8 recirc. pump stained soil removed/leak has been repaired

Inspection Photos
Location Name: Hingley #1
Location ID: 333213



Photo 9 berm has been repaired



Photo 10 berm has been repaired

Inspection Photos
Location Name: Hingley #1
Location ID: 333213



Photo11 Stained soil removed from around Heated Horz. Sep