



99999999

**OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT**☐ NOTICE OF UNSATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801

Denver, CO 80203

☒ NOTICE OF SATISFACTORY INSPECTION

(303)894-2100

API No. 05-	075 - 7481	LEASE NAME:	E. Padroni 2x								
LOCATION:	SE NW 26-9N-52	OPERATOR:	BF Allison								
DATE:	2-18-97	INSPECTOR:	EBB								
Insp. Type:	HR	Insp. Status:	DA								
PA:	Y	N	Pass/Fail:	P	F	Viol.:	Y	N	NOV:	Y	N

**INSPECTION ITEM****COMMENTS****INPUT**

<b>Well ID Signs</b> (Rule 210, 604.c(4))		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)		
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	Cultivated	
<b>Miscellaneous</b>		

RECEIVED

MAR 13 1997

**CORRECTIVE ACTION REQUIRED:**

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00255136