

## Pit Status Evaluation Form

## Pit Overview:

<b>Pit Name:</b> NECKIEN 1	<b>Facility ID:</b> 118695
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> BERGE EXPLORATION INC / 7850	
<b>Updated Operator:</b> RENEGADE OIL & GAS COMPANY LLC 74165	
<b>Form 15 Pit Permit Doc #:</b>	<b>Permit Date:</b>
<b>Related Facilities:</b> STRAWDER 1 (API 05-123-10497) & NECKIEN 1 (API 05-123-10540)	

<b>County:</b> WELD			
<b>Township:</b> 1N	<b>Range:</b> 65W	<b>Section:</b> 28	<b>QQ:</b> SWSE
<b>Original Latitude/ Longitude:</b> 40.016919 / -104.666825			
<b>Updated Latitude/ Longitude:</b> /			
<b>Basis for Location Change:</b>			

### Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts:	<input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                 |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #:                           | Date:           |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 691957                   | Date: 6/26/1986 |
|                                     | Doc #: 691960   | Date: 6/26/1986 |
|                                     | Doc #:  | Date:           |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:             | Date:           |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:                         | Date:           |
| <input type="checkbox"/>            | COGIS Document – Doc #:                               | Date:           |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2223583                        | Date: 1/3/1996  |
| <input checked="" type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: 113239, 118694 |                 |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached)           |                 |
| <input type="checkbox"/>            | Other:  |                 |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date: 9/23/1999**

#### Timing of Pit Closure:

No evidence of a pit at this location.

#### Pit Status Review Summary:

Shared pit/battery btn STRAWDER 1 (API 05-123-10497) & NECKIEN 1 (API 05-123-10540); duplicate pits 118694, 113239, 118695. Based on records review and historic aerial imagery there is no evidence that there was a pit on location. Pit inventory report and inspection reports document a concrete water vault on location. Pit status has been changed to Closed.

