

Inspection Photos

Location Name: Piceance 28-11 Tank Battery & Historical Spill/Release

Location ID: #467201

Inspection Date: November 8, 2019



Photo #1 – Sign at entrance to facility.



Photo #2 – Overview of tank battery from northwest. Note storage of unused pipe (circled) and two 400 bbl ASTs (red arrows).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Piceance 28-11 Tank Battery & Historical Spill/Release

Location ID: #467201

Inspection Date: November 8, 2019



Photo #3 – Lined tank battery area contained snow/ice and fluids on inspection date. No hydrocarbon odors or sheen were observed during inspection. Note trash (water bottle) depicted inside northwest corner of tank battery.



Photo #4 – Unidentified soil stockpile and additional unused equipment located southeast of tank battery.

Inspection Photos

Location Name: Piceance 28-11 Tank Battery & Historical Spill/Release

Location ID: #467201

Inspection Date: November 8, 2019



Photo #5 – Unused liner material stored inside of tank battery (east side).



Photo #6 – View of fenced, scraped area east of tank battery from southeast corner. Open excavations were observed in southeast and northwest corners of this area on inspection date.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Piceance 28-11 Tank Battery & Historical Spill/Release

Location ID: #467201

Inspection Date: November 8, 2019



Photo #7 – Looking into northwest excavation, from east.
No hydrocarbon staining or sheens were observed in visible portions of either excavation on inspection date.



Photo #8 – View of unused 400 bbl ASTs from southeast.
Note open access panel on east tank.



Inspection Photos

Location Name: Piceance 28-11 Tank Battery & Historical Spill/Release

Location ID: #467201

Inspection Date: November 8, 2019



Photo #9 – Unidentified gravel stockpiles located west of separators.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources