

Inspection Photos
Operator: BP America
Location/API #: 067-06481
Date: 11-1-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing here with grasses such as western wheatgrass and shrubby rubber rabbitbrush.



Photo 3. View of the northern project area from the northwestern corner facing westward.



Photo 4. View of reference area vegetation comprised of open gambel oak and mountain mahogany shrubland mosaic with open grass fields and pinyon/juniper stands.