

Inspection Photos
Location Name: Hawkins 5-61-21
Location ID: 4333684



Photo 1 – Pumping Units



Photo 2 – West Tank Battery

Inspection Photos
Location Name: Hawkins 5-61-21
Location ID: 4333684



Photo 3 – East Tank Battery



Photo 4 – East Tank Battery SW corner. Capacity is missing from signs.