

Inspection Photos
Location Name: Dietrich C 06-23
Location ID: 306117



Photo #1 Trash on North side of location. On 9/4/19

Photo #2 Trash on North side of location. On 11/12/19