

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/12/2019

Submitted Date:

11/12/2019

Document Number:

699100567**FIELD INSPECTION FORM**Loc ID 332100 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270169	WELL	SI	06/01/2019	GW	123-21834	ARD C 6-3JI	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash on the north side of Tank Battery needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 603.f .	Date:	12/04/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 270169 Type: WELL API Number: 123-21834 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: T/A, Has Blue "T/A" & Yellow "LTSI" Variance tags.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday November 12, 2019 at approximately 0900, I, Inspector Adam Burns, conducted an Inspection at ARD C 6-3JI of Noble Energy Inc, at API #123-21834 in Weld County, Colorado.</p> <p>While there, I observed a plugged and abandoned location</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Trash on the north side of the Tank Battery needs to be removed for good housekeeping.</p> <p>Comply with Rule 603.f . & corrective date of 12/4/2019</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing education inspections</p>	burnsa	11/12/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699100568	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986211