

Inspection Photos
Location Name: Prospect Valley 22-9
Location ID: 331073



Pic 1 venting wellhead



Pic 2

Inspection Photos
Location Name: Prospect Valley 22-9
Location ID: 331073



Pic 3



Pic 4 water tank no labels, erosion issues

Inspection Photos
Location Name: Prospect Valley 22-9
Location ID: 331073



Pic 5 water tank no labels/erosion issues

