

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/12/2019

Submitted Date:

11/12/2019

Document Number:

696101534

FIELD INSPECTION FORM
 Loc ID 415365 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415430	WELL	SI	06/01/2018	OW	123-31070	70 RANCH USX BB 25-07P	TA

General Comment:

This is WELL & BATTERY inspection.
 Well(s): 1 ; Temporarily Abandoned | TA
 Battery: Abandoned. ALL equipment removed except for Gas meter run & riser.

Abandoned Battery SE corner GPS coordinates: 40.372676, -104.379643
 Reclamation progressing.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment (Gas meter run) at Abandoned battery site. Refer to Rule 603.f.			
Corrective Action:	Remove unused Gas meter run Abandoned battery site. Comply w/ Rule 603.f. See photo #2.			Date: 12/13/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Iron panel			
Corrective Action:				Date:
Equipment:				
Type: Plunger Lift	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Pig Station	# 1			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 0			
Comment:	Battery Abandoned.			
Corrective Action:				Date:

Type: Bradenhead	# 1	
Comment:	Appears plumbed to surface.	
Corrective Action:		Date:
Type: Ancillary equipment	# 0	
Comment:	Battery Abandoned.	
Corrective Action:		Date:
Type: Emission Control Device	# 0	
Comment:	Battery Abandoned.	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment:	Battery Abandoned.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:	Battery Abandoned.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities									
Facility ID:	415430	Type:	WELL	API Number:	123-31070	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>Temporarily Abandoned TA. Battery has been abandoned. Production valves closed at well. Lock-Out / Tag-Out w/ yellow LTSI tag & orange decomission tag. Last prod: 05/2018. Comment: SI/TA well per variance Doc #401474555 (Noble).</div>							
Corrective Action:							Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 11/12/2019 at approximately 16:08 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: 70 RANCH USX BB /25-07P Location ID: 415365 Well Name: 70 Ranch USX BB 25-07P API: 05-123-31070 Location County: Weld County, Colorado Weather: Clear w/ damp areas from prior snow.</p> <p>While there, I observed: Well(s): 1 ; Temporarily Abandoned TA Battery: Abandoned. ALL equipment removed except for Gas meter run & riser.</p> <p>Abandoned Battery SE corner GPS coordinates: 40.372676, -104.379643 Reclamation progressing.</p> <p>During this inspection the following possible compliance issues were observed: 1.) Unused equipment (Gas meter run) at Abandoned battery site. Refer to Rule 603.f. Remove unused Gas meter run Abandoned battery site. Comply w/ Rule 603.f. Corrective Action date: 12/13/2019. See photo #2.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/12/2019