

Inspection Photos
Location Name: Hirsch 24-G Pad
Location ID: 434056



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos
Location Name: Hirsch 24-G Pad
Location ID: 434056



Photo 3: Holes repaired



Photo 4: Pumpjack Sign

Inspection Photos
Location Name: Hirsch 24-G Pad
Location ID: 434056



Photo 5: Pumpjack



Photo 6: Stained soil removed; Trash at back end

Inspection Photos
Location Name: Hirsch 24-G Pad
Location ID: 434056



Photo 7: Trash (behind Hirsch 6-24)



Photo 8: Pumpjack Sign

Inspection Photos
Location Name: Hirsch 24-G Pad
Location ID: 434056



Photo 9: Pumpjack



Photo 10: Stained soil removed

Inspection Photos
Location Name: Hirsch 24-G Pad
Location ID: 434056



Photo 11: Stained soil removed



Photo 12: Trash (behind Hirsch 17-24)

Inspection Photos
Location Name: Hirsch 24-G Pad
Location ID: 434056



Photo 13: Stained soil removed



Photo 14: Stained soil in west separator house (facing tank battery)