

**Inspection Photos**  
**Location Name: Casa Loma Tank Battery**  
**Location ID: 430703**



**Photo 1: Tank Battery Signs**



**Photo 2: Tank Battery**



**Inspection Photos**  
**Location Name: Casa Loma Tank Battery**  
**Location ID: 430703**




**Photo 3: BBLS added to tank BUT NO NFPA PLACARD**



**Photo 4: Tubing removed**

**Inspection Photos**  
**Location Name: Casa Loma Tank Battery**  
**Location ID: 430703**



**Photo 5: Trash Removed**



**Photo 6: Wellhead Sign**



**Inspection Photos**  
**Location Name: Casa Loma Tank Battery**  
**Location ID: 430703**



**Photo 7: Wellhead**



**Photo 8: Wellhead Sign**





**Inspection Photos**  
**Location Name: Casa Loma Tank Battery**  
**Location ID: 430703**



**Photo 9: Wellhead**



**Photo 10: location of other wellheads P&A**