

Inspection Photos
Location Name: BASHOR PC AA /17-17
Location #: 419808



Photo #1

Bashor PC AA 17-17 (05-123-32357) Wellsite
Temporarily Abandoned | TA
Unused chemical tank – remains on site
This is 2nd Follow-up insp.
prior insp.



Photo #2

Bashor PC AA 17-17 (05-123-32357) Wellsite
Temporarily Abandoned | TA
Unused chemical tank – NOW removed

Inspection Photos
Location Name: BASHOR PC AA /17-17
Location #: 419808



Colorado Oil & Gas Conservation Commission
40.49104, -104.46036, 1402.0m, 31°
05/29/2019 02:30:15 PM

Photo #3
Bashor 17-11, 17-14
Bashor PC AA 17-17 – Battery Site
Abandoned – ALL equipment removed
Muddy w/ puddles - *Reclamation progressing*
prior insp.



Colorado Oil & Gas Conservation Commission
40.49104, -104.46041, 1401.0m, 33°
11/13/2019 11:11:35 AM

Photo #4
Bashor 17-11, 17-14
Bashor PC AA 17-17 – Battery Site
Abandoned – ALL equipment removed
Reclamation progressing