

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-08392**  
**Date: 11-6-2019**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing here with smooth brome and ponderosa pine.



Photo 3. View of well pad cut-slope, largely with bare soils on lower slope and sparse grasses such as Indian ricegrass on upper portion of slope.



Photo 4. View of sediment deposition at the toe of the well pad cut slope.



Photo 5. View of reference area west of the well pad, comprised of ponderosa pine forest with gambel oak understory.