

Inspection Photos
Operator: BP America
Location/API #: 067-07153
Date: 11-6-2019



Photo 1. View of the project area from the eastern corner facing center.



Photo 2. View of the northeastern project area from the northern corner facing southeastward. Revegetation is progressing here with smooth brome and western wheatgrass.



Photo 3. View of western cut-slope. Bare soils, erosional channeling and sedimentation observed.



Photo 4. View of sediment deposition (blue arrow) that flows onto the well pad and around facilities.



Photo 5. View of musk thistle rosettes on the well pad.



Photo 6. View of reference area west of the well pad, comprised of ponderosa pine forest with gambel oak understory.