

Inspection Photos

Location Name: NHF-LAURA-65N63W /20NESW

Location #: 332705



Colorado Oil & Gas Conservation Commission
40.3838, -104.46227, 1375.0m, 59°
11/13/2019 01:23:03 PM


Photo #1

NHF-Laura #1 (05-123-19974) Wellsite

Plugged & Abandoned | PA

~ 25 yds.

70 Ranch 4-6-20 wellsite in background



Colorado Oil & Gas Conservation Commission
40.38391, -104.46202, 1372.0m, 75°
11/13/2019 01:24:21 PM

Photo #2

70 Ranch 4-6-20 (05-123-26053) Wellsite

Shut-In | SI

Inspection Photos

Location Name: NHF-LAURA-65N63W /20NESW

Location #: 332705



Photo #3

70 Ranch 4-6-20 Battery site

Inactive | Shut-down

