

Inspection Photos

Location Name: HSR Kammerzell 15-25, Boos 37-25

Location ID: 336613



Colorado Oil And Gas Conservation Commission
40°16'31", -104°50'17", 1443.0m
11/13/2019 01:18:06 PM

Production facility

Inspection Photos
Location Name: HSR Kammerzell 15-25, Boos 37-25
Location ID: 336613



Weeds on 11/4/19



Weeds on 11/13/19

Inspection Photos

Location Name: HSR Kammerzell 15-25, Boos 37-25

Location ID: 336613



Weeds on 11/4/19



Weeds on 11/13/19

Inspection Photos
Location Name: HSR Kammerzell 15-25, Boos 37-25
Location ID: 336613



Unused equipment on 11/4/19



Unused equipment on 11/13/19

Inspection Photos
Location Name: HSR Kammerzell 15-25, Boos 37-25
Location ID: 336613



Unused equipment on 11/4/19



Unused equipment on 11/13/19