

Inspection Photos
Location Name: Boos 20-25
Location ID: 305802



Colorado Oil & Gas Conservation Commission
40.27885, -104.83476, 1427.0m, 207°
11/04/2019 01:23:21 PM

Weeds on 11/4/19



Colorado Oil And Gas Conservation Commission
40°16'44", -104°50'5", 1434.0m, 202°
11/13/2019 02:05:29 PM

Weeds on 11/13/19