

Final Reclamation Inspection

November 13, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

API: 05-123-05482

Inspection Document #: 697500799

Weld County, CO

NWNW Section 31 T8N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: UPRR #13
API: 05-123-05482



Photo 1. Photo taken from the well location, facing East. Photo illustrates equipment has been removed from location. Operator shall comply with Rule 1004.a regarding the timing requirement to complete all final reclamation activities.



Photo 2. Photo taken from the well location, facing North. See comments under Photo 1.