

Inspection Photos

API: 05-055-06102

Operator: OXY USA INC

Inspection Date: 11/6/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06102 | Date: 11/6/2019

Inspection Photos



Photo 1. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06102 | Date: 11/6/2019

Inspection Photos



Photo 2. Noxious weeds appear to have been removed and controlled for the season. Ongoing monitoring and weed control needs to be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06102 | Date: 11/6/2019