

Inspection Photos
Location Name: Spike State CC 6-12
API ID: 123-16201



Photo #1 Well, Sign & Weeds. On 10/22/19



Photo #2 Well, Sign & Weeds. On 11/14/19

Inspection Photos
Location Name: Spike State CC 6-12
API ID: 123-16201



Photo #3 Unused orange fence. On 10/22/19



Photo #4 Unused orange fence. On 11/14/19