

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 1: Wellhead Sign



Photo 2: Wellhead/stained soil

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 3: Stained Soil



Photo 4: Stained Soil

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 5: Wellhead Sign



Photo 6: Wellhead/ stained soil

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 7: Stained Soil



Photo 8: Stained soil

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 9: Wellhead Sign



Photo 10: Wellhead/stained soil

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 11: Stained soil



Photo 12: Wellhead Sign

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 13: Wellhead/stained soil



Photo 14: Stained soil

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 15: Wellhead Sign



Photo 16: Wellhead/stained soil

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879




Photo 17: Stained soil



Photo 18: Unused equipment

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 19: Unused equipment



Photo 20: Weeds west of tank battery

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 21: Separator that has bucket inside



Photo 22: Bucket of unknown substance in separator house

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 23: Separator that has bucket



Photo 24: Bucket of unknown substance in separator house

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 25: Tank Battery Signs



Photo 26: Tank Battery/inadequate berm

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 27: No NFPA placard on tank/Tank not anchored



Photo 28: Tanks not anchored

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 29: Tanks not anchored



Photo 30: Tanks not anchored

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 31: Separator not anchored



Photo 32: Separator not anchored

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 33: Separator not anchored



Photo 34: Separator not anchored

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 35: Separator not anchored



Photo 36: Separator not anchored

Inspection Photos
Location Name: Detterer FD Pad 25-2D
Location ID: 428879



Photo 37: Unused risers