

# *Inspection Photos*

*API#103-06347*

*Operator: Eagle Operating*

*Inspection Number: 692401236*

*Inspection Date: 8/2/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Photo#1:**  
View North over Location center. Arrow indicates riser remaining on site.



**Photo#2:**  
Close up view of riser on site.

August 2, 2019



Photo#3:  
View East over Location center.



Photo#4:  
View of subsidence at base of Marker.

August 2, 2019



Photo#5:  
Noxious and ruderal debris weeds on site.

August 2, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Eagle Operating PA API#103-06347