

Inspection Photos
Location Name: UPRR 42 Pan AM AG 3
Location ID: 311353



Pic 1 stained soil/mechanical issue on wellhead



Pic 2 stockpile of what appears to be contaminated soil.