

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2019

Submitted Date:

11/14/2019

Document Number:

699500296

FIELD INSPECTION FORM

Loc ID 440806 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10110

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC

Address: 1001 17TH STREET #2000

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440807	WELL	PR	08/20/2015	OW	123-41121	Marcus LD 11-374HN	PR
440819	WELL	PR	08/22/2015	OW	123-41131	Marcus LD 11-377HC	PR
442807	SPILL OR RELEASE	CL	08/13/2015		-	SPILL/RELEASE POINT	CL
444366	WELL	PR	04/01/2018	OW	123-42584	Marcus LD 11-378HN	PR
444367	WELL	PR	06/01/2018	OW	123-42585	Marcus LD 11-374HC	PR
444368	WELL	PR	04/01/2018	OW	123-42586	Marcus LD 11-377HN	PR
444369	WELL	PR	06/01/2018	OW	123-42587	Marcus LD 11-379HC	PR
444370	WELL	PR	04/01/2018	OW	123-42588	Marcus LD 11-376HN	PR
445037	WELL	PR	06/01/2018	OW	123-42866	Marcus LD 11-380HN	PR
445038	WELL	PR	12/18/2016	OW	123-42867	Marcus LD 11-379HN	PR
448623	WELL	PR	04/09/2018	OW	123-43945	Marcus LD 11-361HN	PR
448624	WELL	XX	12/09/2016		123-43946	Marcus LD 11-362HN	XX
448748	WELL	XX	06/08/2016		123-43991	Marcus LD 11-362HC	XX
448749	WELL	DG	03/23/2017		123-43992	Marcus LD 11-363HN	DG
448750	WELL	DG	03/21/2017		123-43993	Marcus LD 11-365HC	DG
448751	WELL	DG	03/22/2017		123-43994	Marcus LD 11-364HN	DG
448752	WELL	DG	03/20/2017		123-43995	Marcus LD 11-365HN	DG
448825	WELL	DG	03/17/2017		123-44036	Marcus LD 11-368HN	DG
448826	WELL	DG	03/19/2017		123-44037	Marcus LD 11-367HN	DG
448827	WELL	DG	03/18/2017		123-44038	Marcus LD 11-367HC	DG
448828	WELL	DG	03/12/2017		123-44039	Marcus LD 11-372HC	DG

448829	WELL	PR	04/03/2018	OW	123-44040	Marcus LD 11-371HN	PR
448830	WELL	PR	04/08/2018	OW	123-44041	Marcus LD 11-369HN	PR
448831	WELL	PR	04/02/2018	OW	123-44042	Marcus LD 11-370HC	PR
448832	WELL	PR	04/03/2018	OW	123-44043	Marcus LD 11-372HN	PR
448869	WELL	PR	04/09/2018	OW	123-44053	Marcus LD 11-373HN	PR
451490	SPILL OR RELEASE	CL	08/17/2017		-	Marcus LD Pad 02-361HN	CL
452075	WELL	PR	03/24/2018	OW	123-45380	Marcus LD 11-373HNX	PR
452076	WELL	XX	09/07/2017		123-45381	Marcus LD 11-361HNX	XX
452077	WELL	XX	09/07/2017		123-45382	Marcus LD 11-363HNX	XX
452078	WELL	PR	04/10/2018	OW	123-45383	Marcus LD 11-371HNX	PR
452079	WELL	XX	09/07/2017		123-45384	Marcus LD 11-368HNX	XX
452080	WELL	PR	03/18/2018	OW	123-45385	Marcus LD 11-376HNX	PR
452081	WELL	XX	09/07/2017		123-45386	Marcus LD 11-365HNX	XX
452082	WELL	PR	03/18/2018	OW	123-45387	Marcus LD 11-378HNX	PR
452083	WELL	PR	06/23/2018	OW	123-45388	Marcus LD 11-380HNX	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Sound abatement around location		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>440807</u>	Type: <u>WELL</u>	API Number: <u>123-41121</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>440819</u>	Type: <u>WELL</u>	API Number: <u>123-41131</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>442807</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>CL</u>	Insp. Status: <u>CL</u>
Facility ID: <u>444366</u>	Type: <u>WELL</u>	API Number: <u>123-42584</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>444367</u>	Type: <u>WELL</u>	API Number: <u>123-42585</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>444368</u>	Type: <u>WELL</u>	API Number: <u>123-42586</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>444369</u>	Type: <u>WELL</u>	API Number: <u>123-42587</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>444370</u>	Type: <u>WELL</u>	API Number: <u>123-42588</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>445037</u>	Type: <u>WELL</u>	API Number: <u>123-42866</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>445038</u>	Type: <u>WELL</u>	API Number: <u>123-42867</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>448623</u>	Type: <u>WELL</u>	API Number: <u>123-43945</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>448624</u>	Type: <u>WELL</u>	API Number: <u>123-43946</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>448748</u>	Type: <u>WELL</u>	API Number: <u>123-43991</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>448749</u>	Type: <u>WELL</u>	API Number: <u>123-43992</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448750</u>	Type: <u>WELL</u>	API Number: <u>123-43993</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448751</u>	Type: <u>WELL</u>	API Number: <u>123-43994</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448752</u>	Type: <u>WELL</u>	API Number: <u>123-43995</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448825</u>	Type: <u>WELL</u>	API Number: <u>123-44036</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448826</u>	Type: <u>WELL</u>	API Number: <u>123-44037</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>

Facility ID: 448827	Type: WELL	API Number: 123-44038	Status: DG	Insp. Status: DG
Facility ID: 448828	Type: WELL	API Number: 123-44039	Status: DG	Insp. Status: DG
Facility ID: 448829	Type: WELL	API Number: 123-44040	Status: PR	Insp. Status: PR
Facility ID: 448830	Type: WELL	API Number: 123-44041	Status: PR	Insp. Status: PR
Facility ID: 448831	Type: WELL	API Number: 123-44042	Status: PR	Insp. Status: PR
Facility ID: 448832	Type: WELL	API Number: 123-44043	Status: PR	Insp. Status: PR
Facility ID: 448869	Type: WELL	API Number: 123-44053	Status: PR	Insp. Status: PR
Facility ID: 451490	Type: SPILL OR	API Number: -	Status: CL	Insp. Status: CL
Facility ID: 452075	Type: WELL	API Number: 123-45380	Status: PR	Insp. Status: PR
Facility ID: 452076	Type: WELL	API Number: 123-45381	Status: XX	Insp. Status: XX
Facility ID: 452077	Type: WELL	API Number: 123-45382	Status: XX	Insp. Status: XX
Facility ID: 452078	Type: WELL	API Number: 123-45383	Status: PR	Insp. Status: PR
Facility ID: 452079	Type: WELL	API Number: 123-45384	Status: XX	Insp. Status: XX
Facility ID: 452080	Type: WELL	API Number: 123-45385	Status: PR	Insp. Status: PR
Facility ID: 452081	Type: WELL	API Number: 123-45386	Status: XX	Insp. Status: XX
Facility ID: 452082	Type: WELL	API Number: 123-45387	Status: PR	Insp. Status: PR
Facility ID: 452083	Type: WELL	API Number: 123-45388	Status: PR	Insp. Status: PR

Workover

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Waddles	Pass			
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection perception of soil may have been distorted due to weather conditions.	medinaj	11/14/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500297	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989004