

Final Reclamation Inspection

November 13, 2019

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 318027

Inspection Document #: 697500815

Weld County, CO

NWNE Section 34 T7N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CANAL #2
Location ID: 318027



Photo 1. Photo taken from the location, facing South. Photo illustrates Final Reclamation activities appear to have been performed and hydromulch has been applied to the location.

Note: There was little to no observed germination or establishment throughout the location. Based on aerial imagery, this location may receive water from the lake during certain periods of the year.

Inspection Photos
Location Name: CANAL #2
Location ID: 318027



Photo 2. Photo taken from the location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: CANAL #2
Location ID: 318027



Photo 3. Photo taken from the location, facing Northwest. See comments under Photo 1.