

Final Reclamation Inspection

November 13, 2019

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 434253

Inspection Document #: 697500819

Weld County, CO

NESW Section 7 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Staley Pad /7-J
Location ID: 434253



Photo 1. Photo taken from the northwestern location, facing West. Photo illustrates final reclamation activities have been performed; however, vegetation is not reflective of reference area vegetative levels. Photo illustrate weedy, annual vegetation, Kochia, (inside the red area), as compared to the surrounding reference vegetation.

Inspection Photos
Location Name: Staley Pad /7-J
Location ID: 434253



Photo 2. Photo taken from the northwestern location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Staley Pad /7-J
Location ID: 434253



Photo 3. Photo taken from a portion of the southern location. Photo illustrates bare patches and weedy, annual vegetation.

Inspection Photos
Location Name: Staley Pad /7-J
Location ID: 434253



Photo 4. Photo taken from a portion of the southern location. See comments under Photo 2.

Inspection Photos
Location Name: Staley Pad /7-J
Location ID: 434253



Photo 5. Photo taken from the northwestern location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Staley Pad /7-J
Location ID: 434253



Photo 6. Photo taken from the northwestern location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Staley Pad /7-J
Location ID: 434253



Photo 7. Close up reference photo illustrating the total cover of live perennial vegetation of a reference area which is not reflective within the location.

Inspection Photos
Location Name: Staley Pad /7-J
Location ID: 434253



Photo 8. Photo taken from the southern location, facing North. Photo illustrates what appears to be an active DCP midstream gathering line.