

Inspection Photos
Location Name: HSR Church 14-17
Location ID: 329979



Photo 1 Access rd.



Photo 2 WH no sign

Inspection Photos
Location Name: HSR Church 14-17
Location ID: 329979



Photo 3 TB sign



Photo 4 TB

Inspection Photos
Location Name: HSR Church 14-17
Location ID: 329979



Photo 5 Stained soil appears to be removed

Photo 6 Gas meter run and Heated Horiz. Sep.