

# Inspection Photos

API: 05-071-09512

Operator: PIONEER NATURAL RESOURCES USA INC

Inspection Date: 11/8/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09512 | Date: 11/8/2019

## Inspection Photos



**Photo 1.** Facing north toward the location. There are large berms or terracing across the recontoured site that do not match the surrounding terrain.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09512 | Date: 11/8/2019

## Inspection Photos



**Photo 2.** Facing north toward the location. There are large berms or terracing across the recontoured site that do not match the surrounding terrain.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09512 | Date: 11/8/2019

## Inspection Photos



**Photo 3.** There are some noxious weeds present which include Musk thistle and Common mullein.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09512 | Date: 11/8/2019