

Inspection Photos Location #417777



Location



location

Inspection Photos Location #417777



Stained gravel and paraffin on piping



debris



Inspection Photos Location #417777



debris



debris



Inspection Photos Location #417777



Wildlife escape board not positioned



Wildlife escape board not positioned



Inspection Photos Location #417777



Wildlife escape board not positioned



Wildlife escape board not positioned



Inspection Photos Location #417777



Rat hole not maintained



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources