

Inspection Photos
Location Name: Sheldon R. Sickler
Location ID: 318318



Photo 1 Access rd. weeds have been cut Road is rutted



Photo 2 WH sign operator name has been updated but no emergency contact number.

Inspection Photos
Location Name: Sheldon R. Sickler
Location ID: 318318



Photo 3 PU



Photo 4 Cut Dead weeds lying on location. Dead weeds around WH

Inspection Photos
Location Name: Sheldon R. Sickler
Location ID: 318318



Photo 5 Dead weeds around WH



Photo 6 Dead weeds around Electric panel and transformers.

Inspection Photos
Location Name: Sheldon R. Sickler #4
Location ID: 318318



Photo 7 Dead weeds around PU



Photo 8 Dead weeds around PU.

